An examiner's amendment to the record appears below. Should the changes and/or additions be unacceptable to applicant, an amendment may be filed as provided by 37 CFR 1.312. To ensure consideration of such an amendment, it MUST be submitted no later than the payment of the issue fee.

The following changes have been made to the subject application:

In Specification, page 7,

line 6, "Fig. 2 is a schematic diagram" has been changed to Figs. 2, 2A, 2B are schematic diagrams--.

line 8, "Fig. 4 is a table" has been changed to --Figs. 4, 4A, 4B are tables--.

The Examiner's amendment has been made in order to place the application in a condition for allowance.

REASONS FOR ALLOWANCE

1. The following is an examiner's statement of reasons for allowance:

The cited art of record fails to teach a dusk detecting device having an output that changes in response to an amount of incident light and, means for turning on said controller circuit in response to said dusk detecting device as defined in claim 1, or said controller circuit comprises a plurality of power controllers selectively providing operating power to respective ones of the plural output ports according to a show which defines a pattern for each of said plural output ports and comprises said different programmed patterns as defined in claim 13, or said controller devices are connectable to an input AC voltage supply and each of said programmed patterns is timed relative to the frequency of the input AC voltage supply such that

Application/Control Number: 10/683,724

Art Unit: 2821

said plural controller devices are synchronized by the frequency of said input AC voltage supply as defined in claim 28. Therefore, claims 1-9, 11-19 and 28-36 are presently allowed.

2. Any comments considered necessary by applicant must be submitted no latter than the payment of the issue fee and, to avoid processing delays, should preferably accompany the issue fee. Such submissions should be clearly labeled "Comments on Statement of Reasons for Allowance."

Inquiry

3. Any inquiry concerning this communication or earlier communications from the examiner should be directed to Trinh Vo Dinh whose telephone number is (571) 272-1821. The examiner can normally be reached on Monday to Friday from 9:30AM to 6:00PM.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Don Wong, can be reached on (571) 272-1834. The fax phone number for the organization where this application or proceeding is assigned is 703-872-9306.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free).

Art unit 2821

Trinh Vo Dinh April 22, 2005

rintwodent